

Hedgetrimmer Service



Part No: 2SHS

Price: £37.50 (exc VAT) | £45.00 (inc VAT)

Specifications

Hedgetrimmer Service

* **Change spark plug**

* **Change air filter**

Remove guards and blow airways clear

Grease gearbox

Check idling and max revs

Check and oil

Items marked with "*" are changed as part of the service, but are chargeable separate to the Hedgetrimmer service charge.