

Carpenter Goodwin
31 Bridge St
Leominster
Herefordshire
HR6 8DU
01568 616266
www.carpentergoodwin.co.uk

Strimmer Service



Part No: 2SSS

Price: £37.50 (exc VAT) | £45.00 (inc VAT)

Specifications

Strimmer Service

- * Change spark plug
- * Change air filter

Remove guards and blow airways clean

Grease gearbox

Check and lube driveshaft

Check idling and max revs

Items marked with "*" are changed as part of the service, but are chargeable separate to

1-12-2024 1/2

the Strimmer service charge.

1-12-2024 2/2