

Carpenter Goodwin 31 Bridge St Leominster Herefordshire HR6 8DU 01568 616266 www.carpentergoodwin.co.uk

VPB9505 Engine Repair Kit



Part No: VPB9505 Price: £276.70 (exc VAT) | £332.04 (inc VAT)

Specifications

VPB9505 Engine Repair Kit

Valve train kits are normally required during an Engine overhaul please refer to full Valve Train details

Kit Contents

1 X VPA4028 Top gasket set

- 4 x VPB1140 Semi finished liner
- 4 x VPB2403 Piston
- 4 x VPB4400 Piston ring set
- 4 x VPB7010 Small end bush
- 1 x VPC6023 Bottom gasket set