



Carpenter Goodwin  
31 Bridge St  
Leominster  
Herefordshire  
HR6 8DU  
01568 616266  
[www.carpentergoodwin.co.uk](http://www.carpentergoodwin.co.uk)

## VPB9505 Engine Repair Kit



**Part No:** VPB9505

**Price:** £276.70 (exc VAT) | £332.04 (inc VAT)

### Specifications

VPB9505 Engine Repair Kit

Valve train kits are normally required during an Engine overhaul please refer to full Valve Train details

Kit Contents

1 X VPA4028 Top gasket set

4 x VPB1140 Semi finished liner

4 x VPB2403 Piston

4 x VPB4400 Piston ring set

4 x VPB7010 Small end bush

1 x VPC6023 Bottom gasket set