

Carpenter Goodwin
31 Bridge St
Leominster
Herefordshire
HR6 8DU
01568 616266
www.carpentergoodwin.co.uk

## **VPK2211 - Hydraulic Repair Kit**



Part No: VPK2211

**Price:** £101.69 (exc VAT) | £122.03 (inc VAT)

## **Specifications**

VPK2211 - Hydraulic Repair Kit - Early type

Oil pump Repair Kit to 154547 Pumps with 11mm diameter Oil Gallery hole in Valve Chamber Body

OEM: 1810859M91

12-04-2025 1/1